



**ARDON**  
**WORKWEAR**  
**& OUTDOOR**

# ARDON® COOL TREND®

JACKET



TECHNICAL DATA SHEET



**3D  
SILHOUETTE**



**COTTON**



**REFLECTIVE**



**STANDARD  
100**

PG020 128167  
OETI



**ARDON**<sup>®</sup>  
**WORKWEAR**  
**& OUTDOOR**

# ARDON<sup>®</sup> COOL TREND<sup>®</sup>

JACKET

## ITEM CODE

### MEN'S

H8106	red
H8950	medium blue
H8100	blue
H8220	dark blue – light blue
H8103	green
H8208	grey- orange
H8204	grey - black
H8957	brown
H8964	black
H8800	white – grey

### WOMAN'S

H8190	blue
H9132	grey – orange
H8193	green

## MATERIAL

Outer material

100 % cotton, twill

## GRAMMAGE

260 g/m<sup>2</sup>

## SIZE

men's	S – 5XL
H8100; H8220	XXS – 7XL
woman's	XS – 5XL
H8190; H8193	XS – 4XL

## DESCRIPTION

Classic workwear jacket, strong sturdy material, adjustable width of the cuff, contrasting yoke, zipper with flap, chest pocket with zipper, chest zipper pocket for mobile phone, two lower pockets with zipper, left arm pocket, reflective elements, an intended place for your company logo.

This personal protective equipment is in conformity with the requirements of the following harmonised standard:

**ČSN IN ISO 13688:2013** – Protective clothing – General requirements

The Cool Trend<sup>®</sup> collection meets the requirements for health safety and is a holder of **OEKO-TEX<sup>®</sup>Standard 100 certification, PG020 certificate number 128167 OETI.**

TECHNICAL DATA SHEET





**ARDON®**

**WORKWEAR  
& OUTDOOR**

<b>NUMBER OF PIECES IN CARTON</b>	20 pcs
<b>CARTON WEIGHT</b>	18 kg
<b>CARTON SIZE</b>	0,063 m <sup>3</sup>
<b>UNIT PACKAGING</b>	1 piece

The service life depends on the degree of use and the rate of wear in the given conditions. Improper storage conditions, improper maintenance and care shorten the service life. The warranty period is 24 months. In no case should the warranty period be confused with the service life of the product. With intensive use, the service life may be shorter than the warranty provided.

The product does not contain any substances in concentrations that are known or suspected of adversely affecting the hygiene or health of the user. However, skin irritation is not excluded for sensitive people, in which case do not continue to wear clothing. Avoid fire and sources of intense heat.

No accessories or spare parts are intended for these garments. If clothing is not in use, it is recommended to store it in a dry and well-ventilated area away from direct sunlight. Transport preferably in the original packaging, protect from moisture and extreme temperatures. Dispose of ecologically after use.





**ARDON**<sup>®</sup>  
**WORKWEAR**  
**& OUTDOOR**



TECHNICAL DATA SHEET